6748

St. Mary's County MetCom

Grinder Pump Field Inspection Form



| Date of Inspection | | 1/29/2024 | | | Inspector Initials LN CB | | | | | |
|---|----------------------|---------------------------------------|-------|--------------|--------------------------|------------------|--------|--|--|--|
| Inspection Number | | | • | | | | | | | |
| Property Add | 45076 Lois Marie Ln. | | | | | | | | | |
| Weather Con | Rain | | | | | | | | | |
| Does MetCom | own th | e grinder p | oump? | | | | | | | |
| Yes | No | Unknown, add comments in observations | | | | | | | | |
| What type of pump is this? (Meyers) Barnes Retrofit E1 | | | | | | | | | | |
| Excellent | | 500d Fa | | ir | Poor | Immediate Action | | | | |
| What is the co | ndition | of the cov | er? | | | | | | | |
| Good | | Missing | | Broken | | offset | | | | |
| What type of cover is installed? | | | | | | | | | | |
| Vented | | | | (Non-Vented) | | | | | | |
| Condition of in | | | | - | | | | | | |
| Excellent | \perp | 3ood) | Fa | ır | Poor | Immediate / | Action | | | |
| Is an isolation | valve pr | esent? | | | | | | | | |

No

What is the condition of the electrical panel?

| Excellent | Good | Fair | Poor | Immediate Action | | |
|-----------------|------------------|--------------------|-------------------------|------------------|--|--|
| | | | | , | | |
| he audible ala | rm present and | d functioning? | | | | |
| (Fes | No | | Present, but not tested | | | |
| he visible alar | m present and | functioning? | | | | |
| Yes | No | | Present, but not tested | | | |
| there any ob | vious signs of I | &I (ie. clearwat | er flow)? | (No) | | |
| No signs of I&I | | ns of I&I (weeping | | Major (gushing | | |
| | | • | <u> </u> | , , , , , , | | |
| ier Observatio | ns, any "Imme | diate Action" ta | aken should l | pe described: | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| pairs needed (i | f any) and esti | mated schedule | for complet | ion: | | |
| | | | | | | |
| | | | | | | |

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).