

St. Mary's County MetCom

6379



Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17614 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
-------------------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


vault is in a very small fenced in area touching wooden fence

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6380



Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17618 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom



Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17619 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is an isolation valve present?

Yes	No
-----	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

ABANDONED

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6381



Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17026 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

small fence built around vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6382



Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17628 Clarke Rd		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Near by trees with low overhanging branches

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6857

St. Mary's County MetCom



Grinder Pump Field Inspection Form

Date of Inspection	1/23/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17640 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
-------------------	---------------	----------	----

What is the condition of the vault?

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

vent broken off top of vault cover
ESP switch for alarm
vault was buried between buildings under dirt

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6286

St. Mary's County MetCom



Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17660 Frank's Place Clarke Rd		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6284
WO 3724



Date of Inspection	1/18/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17730 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Roots growing into vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetComGrinder Pump Field Inspection Form

Date of Inspection	1/18/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17746 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6384



Grinder Pump Field Inspection Form

Date of Inspection	1/19/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17747 Clarke Rd.		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6385

Grinder Pump Field Inspection Form

WO 31778



Date of Inspection	1/19/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17752 Clarke Rd.		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> Cloudy <input checked="" type="checkbox"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

0386



Grinder Pump Field Inspection Form

Date of Inspection	1/19/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17765 Clarke Rd.		
Weather Conditions	Rain	<u>Snow</u>	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6387.

WO 31779



Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	1776b Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
-----------------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Vault cover has a hole in it

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6390



Grinder Pump Field Inspection Form

Date of Inspection	1/19/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17769 Clarke Rd.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6392



Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17780 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6395

WO 31780



Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17785 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

Yes	<u>No</u>	Present, but not tested
-----	-----------	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

vault cover chipped off on one bolt hole
Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6398



Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17812 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

ESP switch for alarm

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6405



Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17819 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------


Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6409
WO 31784


Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17827 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Vent broken off top of vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6/13



Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17841 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

ESP switch for alarm

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6416
WO 31789



Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17846 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Is the visible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Vault cover chipped by one bolt hole


Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6418
WD 31790



Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17861 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	<u>Minor signs of I&I (weeping or trickle)</u>	Major (gushing)
-----------------	--	-----------------

Other Observations, any "Immediate Action" taken should be described:

Roots growing into vault near inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6421



Grinder Pump Field Inspection Form

Date of Inspection	1 22 2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17869 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6423

WO 31792



Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17879 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

vent broken off top of vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6425



Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17905 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Is the visible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form



Date of Inspection	1/22/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17909 Clarke Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Is the visible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).