

St. Mary's County MetCom

6749



Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024	Inspector Initials FS CB
Inspection Number		
Property Address	44294 Finnacle Rd.	
Weather Conditions	Rain Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	<u>Retrofit</u>	E1
--------	--------	-----------------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Is the visible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6750
WO 31923



Date of Inspection	1/26/2024	Inspector Initials	FS CB
Inspection Number			
Property Address	44318 Finnicom Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	<u>Retrofit</u>	E1
--------	--------	-----------------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	<u>Poor</u>	Immediate Action
-----------	-------------	------	-------------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	<u>Broken</u>	offset
-------------	---------	---------------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Top of vault below cover is broken

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6752



Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024	Inspector Initials	FS CD
Inspection Number			
Property Address	44338 Finnacle Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	<u>Retrofit</u>	E1
--------	--------	-----------------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Is the visible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6753



Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024	Inspector Initials	FS CB
Inspection Number			
Property Address	44356 FinnacleCom Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	<u>Retrofit</u>	E1
--------	--------	-----------------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Is the visible alarm present and functioning?

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6754



Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024	Inspector Initials	FS CB
Inspection Number			
Property Address	44378 Finnacom Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	<u>Retrofit</u>	E1
--------	--------	-----------------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6756



Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024	Inspector Initials	FS CB
Inspection Number			
Property Address	44400 Finnacom Rd.		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	<u>Retrofit</u>	E1
--------	--------	-----------------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6755



Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024	Inspector Initials	FS CB
Inspection Number			
Property Address	44424 Finna.com Rd.		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	<u>Retrofit</u>	E1
--------	--------	-----------------	----

What is the condition of the vault?

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

vault is in the middle of some shrubs

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6757



Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024	Inspector Initials	FS CB
Inspection Number			
Property Address	44472 Finnacom Rd.		
Weather Conditions	Rain 44472 Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

During high tide and rain events, vault cover is underwater

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).