

6577



Grinder Pump Field Inspection Form

| | | | |
|---------------------------|----------------------|---------------------------|---------------------|
| Date of Inspection | 1/12/24 | Inspector Initials | mam |
| Inspection Number | | | |
| Property Address | 45966 O'CONNORS LANE | | |
| Weather Conditions | Rain | Snow | <u>Sunny</u> Cloudy |

Does MetCom own the grinder pump?

| | | |
|------------|----|---------------------------------------|
| <u>Yes</u> | No | Unknown, add comments in observations |
|------------|----|---------------------------------------|

What type of pump is this?

| | | | |
|--------|---------------|----------|----|
| Meyers | <u>Barnes</u> | Retrofit | E1 |
|--------|---------------|----------|----|

What is the condition of the vault?

| | | | | |
|-----------|-------------|------|------|------------------|
| Excellent | <u>Good</u> | Fair | Poor | Immediate Action |
|-----------|-------------|------|------|------------------|

What is the condition of the cover?

| | | | |
|-------------|---------|--------|--------|
| <u>Good</u> | Missing | Broken | offset |
|-------------|---------|--------|--------|

What type of cover is installed?

| | |
|--------|-------------------|
| Vented | <u>Non-Vented</u> |
|--------|-------------------|

Condition of interior fixtures (guide rails, electrical connections, etc.)

| | | | | |
|-----------|-------------|------|------|------------------|
| Excellent | <u>Good</u> | Fair | Poor | Immediate Action |
|-----------|-------------|------|------|------------------|

Is an isolation valve present?

| | |
|-----|-----------|
| Yes | <u>No</u> |
|-----|-----------|

What is the condition of the electrical panel?

| | | | | |
|-----------|------|------|------|------------------|
| Excellent | Good | Fair | Poor | Immediate Action |
|-----------|------|------|------|------------------|

Is the audible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Is the visible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Are there any accessibility issues (shrubs, trees, fences)?

| | |
|--|----|
| Yes, note issues below in observations | No |
|--|----|

Are there any obvious signs of I&I (ie. clearwater flow)?

| | | |
|-----------------|---|-----------------|
| No signs of I&I | Minor signs of I&I (weeping or trickle) | Major (gushing) |
|-----------------|---|-----------------|

Other Observations, any "Immediate Action" taken should be described:

| |
|--|
| |
| |
| |

Repairs needed (if any) and estimated schedule for completion:

| |
|--|
| |
| |
| |

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



Grinder Pump Field Inspection Form

| | | | |
|---------------------------|-------------------|---------------------------|---------------------|
| Date of Inspection | 1/12/24 | Inspector Initials | mm |
| Inspection Number | | | |
| Property Address | 45970 OCOMORSLANE | | |
| Weather Conditions | Rain | Snow | <u>Sunny</u> Cloudy |

Does MetCom own the grinder pump?

| | | |
|------------|----|---------------------------------------|
| <u>Yes</u> | No | Unknown, add comments in observations |
|------------|----|---------------------------------------|

What type of pump is this?

| | | | |
|--------|---------------|----------|----|
| Meyers | <u>Barnes</u> | Retrofit | E1 |
|--------|---------------|----------|----|

What is the condition of the vault?

| | | | | |
|-----------|-------------|------|------|------------------|
| Excellent | <u>Good</u> | Fair | Poor | Immediate Action |
|-----------|-------------|------|------|------------------|

What is the condition of the cover?

| | | | |
|-------------|---------|--------|--------|
| <u>Good</u> | Missing | Broken | offset |
|-------------|---------|--------|--------|

What type of cover is installed?

| | |
|--------|-------------------|
| Vented | <u>Non-Vented</u> |
|--------|-------------------|

Condition of interior fixtures (guide rails, electrical connections, etc.)

| | | | | |
|-----------|-------------|------|------|------------------|
| Excellent | <u>Good</u> | Fair | Poor | Immediate Action |
|-----------|-------------|------|------|------------------|

Is an isolation valve present?

| | |
|-----|-----------|
| Yes | <u>No</u> |
|-----|-----------|

What is the condition of the electrical panel?

| | | | | |
|-----------|------|------|------|------------------|
| Excellent | Good | Fair | Poor | Immediate Action |
|-----------|------|------|------|------------------|

Is the audible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Is the visible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Are there any accessibility issues (shrubs, trees, fences)?

| | |
|--|----|
| Yes, note issues below in observations | No |
|--|----|

Are there any obvious signs of I&I (ie. clearwater flow)?

| | | |
|-----------------|---|-----------------|
| No signs of I&I | Minor signs of I&I (weeping or trickle) | Major (gushing) |
|-----------------|---|-----------------|

Other Observations, any "Immediate Action" taken should be described:

| |
|--|
| |
| |
| |

Repairs needed (if any) and estimated schedule for completion:

| |
|--|
| |
| |
| |

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6580



Grinder Pump Field Inspection Form

| | | | |
|---------------------------|--------------------|---------------------------|---------------------|
| Date of Inspection | 11/2/24 | Inspector Initials | mm |
| Inspection Number | | | |
| Property Address | 45972 OCONNORSLANE | | |
| Weather Conditions | Rain | Snow | <u>Sunny</u> Cloudy |

Does MetCom own the grinder pump?

| | | |
|------------|----|---------------------------------------|
| <u>Yes</u> | No | Unknown, add comments in observations |
|------------|----|---------------------------------------|

What type of pump is this?

| | | | |
|--------|---------------|----------|----|
| Meyers | <u>Barnes</u> | Retrofit | E1 |
|--------|---------------|----------|----|

What is the condition of the vault?

| | | | | |
|-----------|-------------|------|------|------------------|
| Excellent | <u>Good</u> | Fair | Poor | Immediate Action |
|-----------|-------------|------|------|------------------|

What is the condition of the cover?

| | | | |
|-------------|---------|--------|--------|
| <u>Good</u> | Missing | Broken | offset |
|-------------|---------|--------|--------|

What type of cover is installed?

| | |
|--------|-------------------|
| Vented | <u>Non-Vented</u> |
|--------|-------------------|

Condition of interior fixtures (guide rails, electrical connections, etc.)

| | | | | |
|-----------|-------------|------|------|------------------|
| Excellent | <u>Good</u> | Fair | Poor | Immediate Action |
|-----------|-------------|------|------|------------------|

Is an isolation valve present?

| | |
|-----|-----------|
| Yes | <u>No</u> |
|-----|-----------|

What is the condition of the electrical panel?

| | | | | |
|-----------|------|------|------|------------------|
| Excellent | Good | Fair | Poor | Immediate Action |
|-----------|------|------|------|------------------|

Is the audible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Is the visible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Are there any accessibility issues (shrubs, trees, fences)?

| | |
|--|----|
| Yes, note issues below in observations | No |
|--|----|

Are there any obvious signs of I&I (ie. clearwater flow)?

| | | |
|-----------------|---|-----------------|
| No signs of I&I | Minor signs of I&I (weeping or trickle) | Major (gushing) |
|-----------------|---|-----------------|

Other Observations, any "Immediate Action" taken should be described:

| |
|--|
| |
| |
| |

Repairs needed (if any) and estimated schedule for completion:


| |
|--|
| |
| |
| |

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6582
WD 31841



| | | | |
|---------------------------|--------------------|---------------------------|---------------------|
| Date of Inspection | 1/12/24 | Inspector Initials | mm |
| Inspection Number | | | |
| Property Address | 46006 OGDONOS LANE | | |
| Weather Conditions | Rain | Snow | <u>Sunny</u> Cloudy |

Does MetCom own the grinder pump?

| | | |
|------------|----|---------------------------------------|
| <u>Yes</u> | No | Unknown, add comments in observations |
|------------|----|---------------------------------------|

What type of pump is this?

| | | | |
|--------|---------------|----------|----|
| Meyers | <u>Barnes</u> | Retrofit | E1 |
|--------|---------------|----------|----|

What is the condition of the vault?

| | | | | |
|-----------|-------------|------|------|------------------|
| Excellent | <u>Good</u> | Fair | Poor | Immediate Action |
|-----------|-------------|------|------|------------------|

What is the condition of the cover?

| | | | |
|------|---------|---------------|--------|
| Good | Missing | <u>Broken</u> | offset |
|------|---------|---------------|--------|

What type of cover is installed?

| | |
|--------|-------------------|
| Vented | <u>Non-Vented</u> |
|--------|-------------------|

Condition of interior fixtures (guide rails, electrical connections, etc.)

| | | | | |
|-----------|-------------|------|------|------------------|
| Excellent | <u>Good</u> | Fair | Poor | Immediate Action |
|-----------|-------------|------|------|------------------|

Is an isolation valve present?

| | |
|------------|---------------|
| <u>Yes</u> | No |
|------------|---------------|

What is the condition of the electrical panel?

| | | | | |
|-----------|------|------|------|------------------|
| Excellent | Good | Fair | Poor | Immediate Action |
|-----------|------|------|------|------------------|

Is the audible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Is the visible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Are there any accessibility issues (shrubs, trees, fences)?

| | |
|--|----|
| Yes, note issues below in observations | No |
|--|----|

Are there any obvious signs of I&I (ie. clearwater flow)?

| | | |
|-----------------|---|-----------------|
| No signs of I&I | Minor signs of I&I (weeping or trickle) | Major (gushing) |
|-----------------|---|-----------------|

Other Observations, any "Immediate Action" taken should be described:

| |
|--|
| |
| |
| |

Repairs needed (if any) and estimated schedule for completion:

| |
|---------------------------------|
| NEED TO REPLACE COVER AND RISER |
| |
| |

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6583



Grinder Pump Field Inspection Form

| | | | |
|---------------------------|-------------------|---------------------------|--------|
| Date of Inspection | 1/12/24 | Inspector Initials | mm |
| Inspection Number | | | |
| Property Address | 46015 OCOMOR LANE | | |
| Weather Conditions | Rain | Snow | Sunny |
| | | | Cloudy |

Does MetCom own the grinder pump?

| | | |
|--------------------------------------|--------------------------|---|
| <input checked="" type="radio"/> Yes | <input type="radio"/> No | <input type="radio"/> Unknown, add comments in observations |
|--------------------------------------|--------------------------|---|

What type of pump is this?

| | | | |
|------------------------------|---|--------------------------------|--------------------------|
| <input type="radio"/> Meyers | <input checked="" type="radio"/> Barnes | <input type="radio"/> Retrofit | <input type="radio"/> E1 |
|------------------------------|---|--------------------------------|--------------------------|

What is the condition of the vault?

| | | | | |
|---------------------------------|---------------------------------------|----------------------------|----------------------------|--|
| <input type="radio"/> Excellent | <input checked="" type="radio"/> Good | <input type="radio"/> Fair | <input type="radio"/> Poor | <input type="radio"/> Immediate Action |
|---------------------------------|---------------------------------------|----------------------------|----------------------------|--|

What is the condition of the cover?

| | | | |
|---------------------------------------|-------------------------------|------------------------------|------------------------------|
| <input checked="" type="radio"/> Good | <input type="radio"/> Missing | <input type="radio"/> Broken | <input type="radio"/> offset |
|---------------------------------------|-------------------------------|------------------------------|------------------------------|

What type of cover is installed?

| | |
|------------------------------|---|
| <input type="radio"/> Vented | <input checked="" type="radio"/> Non-Vented |
|------------------------------|---|

Condition of interior fixtures (guide rails, electrical connections, etc.)

| | | | | |
|---------------------------------|---------------------------------------|----------------------------|----------------------------|--|
| <input type="radio"/> Excellent | <input checked="" type="radio"/> Good | <input type="radio"/> Fair | <input type="radio"/> Poor | <input type="radio"/> Immediate Action |
|---------------------------------|---------------------------------------|----------------------------|----------------------------|--|

Is an isolation valve present?

| | |
|--------------------------------------|--------------------------|
| <input checked="" type="radio"/> Yes | <input type="radio"/> No |
|--------------------------------------|--------------------------|

What is the condition of the electrical panel?

| | | | | |
|-----------|------|------|------|------------------|
| Excellent | Good | Fair | Poor | Immediate Action |
|-----------|------|------|------|------------------|

Is the audible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Is the visible alarm present and functioning?

| | | |
|-----|----|-------------------------|
| Yes | No | Present, but not tested |
|-----|----|-------------------------|

Are there any accessibility issues (shrubs, trees, fences)?

| | |
|--|----|
| Yes, note issues below in observations | No |
|--|----|

Are there any obvious signs of I&I (ie. clearwater flow)?

| | | |
|-----------------|---|-----------------|
| No signs of I&I | Minor signs of I&I (weeping or trickle) | Major (gushing) |
|-----------------|---|-----------------|

Other Observations, any "Immediate Action" taken should be described:

| |
|--|
| |
| |
| |

Repairs needed (if any) and estimated schedule for completion:

| |
|--|
| |
| |
| |

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).