St. Mary's County MetCom



Grinder Pump Field Inspection Form



Date of Inspec	tion	1/18/2	24	Inspector I	nitials	ジャナー
Inspection Nun	nber	, , ,				
Property Addre	ess	46325	9125A+	MARE WAY	Carre	-
Weather Cond	itions	Rain	Snow		unny	Cloud
oes MetCom o	wn the	e grinder p	ump?			
Yes 1	Vo	Ur	nknown, ac	ld comments ir	n observ	vations
/hat type of pu	ımp is t	this?				
(Meyers)		Barnes	5	Retrofit		E1
Excellent	Ğ	ood)	fair	Poor	lmn	nediate Action
	-		Fair	Poor	Imm	nediate Action
	-		Fair	Poor	Imm	nediate Action
/hat is the cond	dition o	of the cove	Fair			
/hat is the cond	dition o	Missing nstalled?	Fair r?	Broken Non-V	rented)	offset
/hat is the cond	ver is in	Missing nstalled?	Fair r?	Broken Non-V	rented)	
hat is the cond Good hat type of covered to the condition of interesting	ver is inented	Missing nstalled?	Fair r?	Broken Non-V	rented)	offset tc.)

What is the condition of the electrical panel? Excellent Good Fair Poor Immediate Action

Excellent	Good	Fair	Poor	Immediate Action
he audible ala	arm present and f	unctioning?		
Yes	No		Present, but	not tested
he visible ala	rm present and fu	nctioning?		
Yes	No		Present, but	not tested
	ovious signs of I&I			Major (gushing)
No signs of 1&	D Willion Signs	or ior (weep	ng or trickle)	iviajor (gustimg)
ther Observati	ons, any "Immedi	ate Action" t	aken should	be described:
,				
	//c \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	ادناد ممامم الدعم	a fan aansalas	hi - m .

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).