### St. Mary's County MetCom

# **Grinder Pump Field Inspection Form**



Date of Inspection	1/11/2024	1	Inchaetar Initial		
Inspection Number	111 602		Inspector Initials	LN	CB
Property Address	45382	Locust	<b>£</b> †		
<b>Weather Conditions</b>	Rain	Snow			
			Sunny	- 1	Cloudy

### Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations
		Onknown, add comments in observations

#### What type of pump is this?

Meyers			
TVICYCI3	(Barnes)	Retrofit	
			F1
			<u> </u>

### What is the condition of the vault?

Excellent		I		
Crycellette	Good	Fair	Poor	les la company
			P001	Immediate Action

### What is the condition of the cover?

(Good)			
Good	Missing	Broken	offcot
			offset

### What type of cover is installed?

Vented	
- Ontou	Non-Vented

# Condition of interior fixtures (guide rails, electrical connections, etc.)

				, e,
Excellent	Good	Fair	Poor	Immediate Action

#### Is an isolation valve present?

Yes	No
	110


## What is the condition of the electrical panel?

cellent	Good	Fair	Poor	Immediate Action
	and and	I functioning?		
audible ala	rm present and	Tunctioning.		
Yes	No		Present, but	not tested
109				
_		functioning?		
visible alar	rm present and	Tunctioning:		
	No		Present, but	not tested
Yes			Present, but	not tested
Yes	No			not tested
Yes				not tested
Yes here any ac	No ccessibility issue	es (shrubs, tree		not tested
Yes here any ac	No	es (shrubs, tree		
here any ac	No ccessibility issue sues below in o	es (shrubs, tree bservations	s, fences)?	
there any ac	No ccessibility issue sues below in o	es (shrubs, tree bservations	s, fences)?	
there any ac	No ccessibility issues sues below in o	es (shrubs, tree bservations	s, fences)?	No

Other Observations, any "Immediate Action" taken should be described:

Other Observations, any	
Tall se	agrass around vault cover

Repairs needed (if any) and estimated schedule for completion:



Photos should be sent to <a href="mailto:opadmin@metcom.org">opadmin@metcom.org</a> with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

## St. Mary's County MetCom

# **Grinder Pump Field Inspection Form**



Date of Inspection	1/11/20	24	Inchesta	1
<b>Inspection Number</b>	111100		Inspector	Initials LN CB
<b>Property Address</b>	45395	Locust	24	
Weather Conditions	Rain	Snow		
		311044	6	unny Cloudy
Does MetCom own t	he grinder pu	mp?		
(Yes) No	Link	(nown add	000000000000000000000000000000000000000	
		diowii, aud	comments in	observations
What type of pump is	s this?			
Meyers	Barnes		Retrofit	E1
What is the condition  Excellent	of the vault?	Fair	Poor	Immediate Action
			1 001	mineulate Action
What is the condition	of the cover?			
Good	Missing		Broken	offset
What type of cover is i	nstalled?			
Vented			Non Va	
			Non-Ve	ented
Condition of interior fix	ctures (guide	rails, electr	ical connection	ons, etc.)
	ood	Fair	Poor	Immediate Action

# Is an isolation valve present?

Voc	
res	No

Poor

Immediate Action

### What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
Is the audible alar	m present and	functioning?		

Present, but not tested

## Is the visible alarm present and functioning?

Yes

Is the visible alari	ii present and taxes	
Yes	No	Present, but not tested

## Are there any accessibility issues (shrubs, trees, fences)?

No

Are there any accessionity loss to the
Yes, note issues below in observations

## Are there any obvious signs of I&I (ie. clearwater flow)?

Ale fliele ally oppose		
No signs of 18/	Minor signs of I&I (weeping or trickle)	Major (gushing)
Other Observations,	any "Immediate Action" taken should be de	escribed:

	Illilleulate Action taken and
Pump	has ESP switch for alarm

# Repairs needed (if any) and estimated schedule for completion:

R	epairs needed (if any) and estimated schedule for completion.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).