St. Mary's County MetCom

6237

Grinder Pump Field Inspection Form



Date of Inspection	1/8/20	24	Inspector Initials	LN	0.0
Inspection Number			inspector mitturs	LN	CB
Property Address	17495	H0114 87			
Weather Conditions	Rain	Snow	Sunny		Cloudy
			Sami		cloudy

Does	MetCom	own	the	grinder	pump?
------	--------	-----	-----	---------	-------

(Yes/	No	I for London
	140	Unknown, add comments in observations
		, and definitely in observations

What type of pump is this?

Meyers	(D		3.60
IVICYCIS	∪ Barnes∕	Retrofit	F1
			£1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	N 4: .		
	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

				-, -, -, -, -, -, -, -, -, -, -, -, -, -
Excellent	Cood	-		
Execution	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No
	110

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
Is the audible al	arm present and	I functioning?		
Yes	No		Present, bu	t not tested
Is the visible ala	arm present and	functioning?		
				•
Yes	No		Present, bu	t not tested

Are there any obvious signs of I&I (ie. clearwater flow)?

Yes, note issues below in observations

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
Other Observations	s, any "Immediate Action" taken should be	described:

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Is an isolation valve present?

Yes

Grinder Pump Field Inspection Form



Date of Inspection	18/2024		Inspector In	itials	LN	10
Inspection Number	101		- P		<u></u>	
Property Address	17508	Holly S:	<u>}.</u>			
Weather Conditions	Rain	Snow		nny		Cloud
Yes No			omments in o	observ	ations	
/hat type of pump is t	this?					
Meyers	Barnes	F	Retrofit		 E1	
				2 1924		ŝ
hat is the condition of Excellent G	ood	Fair	Poor	Imme	ediate	Action
Excellent G	ood		Poor	Imme	ediate	
Excellent G	ood of the cover? Missing					Action
hat is the condition of Good Good hat type of cover is in Vented ndition of interior fixed	ood of the cover? Missing estalled? tures (guide rai	B	Non-Ver	ons, etc	offse	

No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
- LAGOIIG	<u></u>			

ls	the	audible	alarm	present	and	functioning?
----	-----	---------	-------	---------	-----	--------------

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested


Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	(No)

Are there any obvious signs of I&I (ie. clearwater flow)?

•	_	
No signs of Rel	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:



Repairs needed (if any) and estimated schedule for completion:

,	
١	
1	
١	
1	
1	
i	

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).