10856

St. Mary's County MetCom

Grinder Pump Field Inspection Form



1/24/	2024	Inspector Initia	IS LN	CB
18200	Peninsulas	(4,		
Rain	Snow	XXXX INV		Cloudy
	13-11	18200 Peninsulas	18200 Peninsulus Ct.	18200 Peninsulus Ct.

Does MetCom own the grinder pump?

MACI	No	Unknown add comments in about the
/ 103/	140	Unknown, add comments in observations

What type of pump is this?

	T		
(Meyers)	Darnes	ם בי כיי	= 4
(ivieyers)	barnes	Retrofit	F1
	L		<u></u>

What is the condition of the vault?

		1			
6	Excellent)	Good	Fair	Poor	Immediate Action
					1

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent)	Good	Fair	Poor	Immediate Action
			1	

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Good Fair	Poor	Immediate Action
Good Fair	Poor	Immediate Action

Yes	No	Present, but not t	ested
the visible alarm	present and functioning?		
Yes	No	Present, but not t	ested
e there any acce	ssibility issues (shrubs, tree	es, fences)?	
Yes, note issue	s below in observations	(No	
	ous signs of I&I (ie. clearwa		
there any obvi		iter flow)?	Major (gushing
there any obvious of I&I	ous signs of I&I (ie. clearwa	iter flow)? ing or trickle)	Major (gushing)
e there any obvious signs of I&I	ous signs of I&I (ie. clearwa Minor signs of I&I (weep	iter flow)? ing or trickle)	Major (gushing)
e there any obvi	ous signs of I&I (ie. clearwa Minor signs of I&I (weep	iter flow)? ing or trickle)	Major (gushing)

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).