

St. Mary's County MetCom

6610



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm	
Inspection Number				
Property Address	17191 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="checkbox"/> Unknown, add comments in observations
--------------------------------------	--------------------------	--

What type of pump is this?

<input type="checkbox"/> Meyers	<input checked="" type="checkbox"/> Barnes	<input type="checkbox"/> Retrofit	<input type="checkbox"/> E1
---------------------------------	--	-----------------------------------	-----------------------------

What is the condition of the vault?

<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
------------------------------------	--	-------------------------------	-------------------------------	---

What is the condition of the cover?

<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Missing	<input type="checkbox"/> Broken	<input type="checkbox"/> offset
--	----------------------------------	---------------------------------	---------------------------------

What type of cover is installed?

<input checked="" type="checkbox"/> Vented	<input type="checkbox"/> Non-Vented
--	-------------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
------------------------------------	--	-------------------------------	-------------------------------	---

Is an isolation valve present?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
---	-----------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6612



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17160 Piney Point RD #1 / Trot Line Way		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6663



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17160 Pine Point Rd #2 / Trot Line Way		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6014



Grinder Pump Field Inspection Form

Date of Inspection	1/24/14	Inspector Initials	mm	
Inspection Number				
Property Address	17162 PINEY POINT RD / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

4615



Grinder Pump Field Inspection Form

Date of Inspection	11/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17164 Pine Point Ln / Trot Line way		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6616

# St. Mary's County MetCom



## Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17106 Pine Point Rd / 1st Line Way		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6617



Grinder Pump Field Inspection Form

Date of Inspection	11/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17172 Pine Pointes rd / Trot Line Way		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**


No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6618



Grinder Pump Field Inspection Form

Date of Inspection	11/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17174 Piney Pointe Rd / Trot Line Way		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



6619



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm	
Inspection Number				
Property Address	17176 Ping Point RD / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6620



Grinder Pump Field Inspection Form

Date of Inspection	11/24/14	Inspector Initials	mm
Inspection Number			
Property Address	17178 Ring Point rd / Trout Line Way		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE CLEANED OUT
BUSH IN FRONT OF PANEL

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6621



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm	
Inspection Number				
Property Address	17180 Piny Point Rd / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:



Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF PANEL

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

# St. Mary's County MetCom

6622



## Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm	
Inspection Number				
Property Address	17182 Piney Point Rd / Trout Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6623



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm	
Inspection Number				
Property Address	17194 Pinyon Pointe Ln			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	Unknown, add comments in observations
--------------------------------------	--------------------------	---------------------------------------

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6624



Grinder Pump Field Inspection Form

Date of Inspection	11/24/14	Inspector Initials	mm	
Inspection Number				
Property Address	17200 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6625

WO 31869



Date of Inspection	1/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17203 Dinky Point Rd		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

COVER IS CRACKED

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

VAULT NEEDS TO BE PUMPED OUT
NO POWER GOING TO PANEL

Repairs needed (if any) and estimated schedule for completion:

COVER IS CRACKED
BUSH IN FRONT OF PANEL

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6026



Grinder Pump Field Inspection Form

Date of Inspection	11/24/24	Inspector Initials	man	
Inspection Number				
Property Address	17213 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6628



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17214 Piney Point RD		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6629



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17216 Pines Point RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6630

WO 31870



Date of Inspection	1/24/24	Inspector Initials	mam	
Inspection Number				
Property Address	17217 PINEY POINT RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	Unknown, add comments in observations
--------------------------------------	--------------------------	---------------------------------------

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input type="radio"/> Good	<input type="radio"/> Missing	<input checked="" type="radio"/> Broken	<input type="radio"/> offset
----------------------------	-------------------------------	---	------------------------------

HOLE IN THE COVER.

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF ELECTRICAL PANEL
HOLE HOLE IN THE COVER

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6631  
WO 31871



Date of Inspection	1/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17222 Dingy Point Ln		
Weather Conditions	Rain	Show	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF PANEL
VAULT NEEDS TO BE CLEANED

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



6632



St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17232 Pine Point Rd		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> Cloudy <input checked="" type="checkbox"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="checkbox"/> Unknown, add comments in observations
--------------------------------------	--------------------------	--

What type of pump is this?

<input type="checkbox"/> Meyers	<input checked="" type="checkbox"/> Barnes	<input type="checkbox"/> Retrofit	<input type="checkbox"/> E1
---------------------------------	--	-----------------------------------	-----------------------------

What is the condition of the vault?

<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
------------------------------------	--	-------------------------------	-------------------------------	---

What is the condition of the cover?

<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Missing	<input type="checkbox"/> Broken	<input type="checkbox"/> offset
--	----------------------------------	---------------------------------	---------------------------------

What type of cover is installed?

<input checked="" type="checkbox"/> Vented	<input type="checkbox"/> Non-Vented
--	-------------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
------------------------------------	--	-------------------------------	-------------------------------	---

Is an isolation valve present?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
---	-----------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6633



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17236 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny <input type="radio"/> Cloudy <input checked="" type="radio"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="checkbox"/> Unknown, add comments in observations
--------------------------------------	--------------------------	--

What type of pump is this?

<input type="checkbox"/> Meyers	<input checked="" type="checkbox"/> Barnes	<input type="checkbox"/> Retrofit	<input type="checkbox"/> E1
---------------------------------	--	-----------------------------------	-----------------------------

What is the condition of the vault?

<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
------------------------------------	--	-------------------------------	-------------------------------	---

What is the condition of the cover?

<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Missing	<input type="checkbox"/> Broken	<input type="checkbox"/> offset
--	----------------------------------	---------------------------------	---------------------------------

What type of cover is installed?

<input checked="" type="checkbox"/> Vented	<input type="checkbox"/> Non-Vented
--	-------------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
------------------------------------	--	-------------------------------	-------------------------------	---

Is an isolation valve present?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
---	-----------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6634  
WO 31872



Date of Inspection	1/24/24	Inspector Initials	mm	
Inspection Number				
Property Address	17242 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations
-----	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	Retrofit	E1
--------	--------	----------	----

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

What is the condition of the cover?

Good	Missing	Broken	offset
------	---------	--------	--------

What type of cover is installed?

Vented	Non-Vented
--------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is an isolation valve present?

Yes	No
-----	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

NEED TO INSTALL BOLTS AND WASHERS ON COVER

Repairs needed (if any) and estimated schedule for completion:


<del>NEED TO INSTALL BOLTS AND WASHERS ON COVER</del>

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6635

St. Mary's County MetCom

Grinder Pump Field Inspection Form



<b>Date of Inspection</b>	1/24/24	<b>Inspector Initials</b>	mm
<b>Inspection Number</b>			
<b>Property Address</b>	17244 Piney Point Rd		
<b>Weather Conditions</b>	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6636



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm
Inspection Number			
Property Address	17246 PINEY POINT RD		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6637

**Grinder Pump Field Inspection Form**

WO 31873



<b>Date of Inspection</b>	1/24/24	<b>Inspector Initials</b>	mm	
<b>Inspection Number</b>				
<b>Property Address</b>	17256 PINEY POINT RD			
<b>Weather Conditions</b>	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE CLEANED OUT

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6638

Grinder Pump Field Inspection Form

WO 31874



Date of Inspection	11/25/24	Inspector Initials	man
Inspection Number			
Property Address	17309 Piney Point RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input checked="" type="radio"/> E1
------------------------------	------------------------------	--------------------------------	-------------------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input type="radio"/> Good	<input checked="" type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	----------------------------	---------------------------------------	----------------------------	--

What is the condition of the cover?

<input type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input checked="" type="radio"/> offset
----------------------------	-------------------------------	------------------------------	---

NOT FITTING PROPERLY

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

*COULD NOT FITTING PROPERLY*

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

<i>COULD NOT FITTING PROPERLY</i>

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6639

WO 31875



Date of Inspection	1/25/24	Inspector Initials	mm	
Inspection Number				
Property Address	17330 A Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input checked="" type="radio"/> E1
------------------------------	------------------------------	--------------------------------	-------------------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input checked="" type="radio"/> Immediate Action
---------------------------------	----------------------------	----------------------------	----------------------------	---

SIDE OF VAULT IS CRACKED

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

VAULT IS CRACKED

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:



Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



6640

St. Mary's County MetCom

Grinder Pump Field Inspection Form



Date of Inspection	1/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17330 B Ding Point RD		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> Cloudy <input checked="" type="checkbox"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input checked="" type="radio"/> E1
------------------------------	------------------------------	--------------------------------	-------------------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6641



Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	Inspector Initials	mm	
Inspection Number				
Property Address	17334 PINEY POINT RD.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6642



Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17342 Piney Point RD		
Weather Conditions	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input checked="" type="radio"/> E1
------------------------------	------------------------------	--------------------------------	-------------------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
----------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6643



Grinder Pump Field Inspection Form

Date of Inspection	11/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17344 PINEY POINT RD		
Weather Conditions	<u>Rain</u>	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	Retrofit	<u>E1</u>
--------	--------	----------	-----------

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

**Is the visible alarm present and functioning?**

Yes	No	<u>Present, but not tested</u>
-----	----	--------------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6644

Grinder Pump Field Inspection Form

WO 31876



Date of Inspection	1/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17346 Piney Point RD		
Weather Conditions	<u>Rain</u>	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	Retrofit	<u>E1</u>
--------	--------	----------	-----------

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	<u>Immediate Action</u>
-----------	------	------	------	-------------------------

COVER MISSING OVER BREAKERS

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Cover missing over breakers

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Cover missing over breakers on panel.

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6045



Grinder Pump Field Inspection Form

Date of Inspection	11/05/24	Inspector Initials	mm
Inspection Number			
Property Address	17365 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6646



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	11/25/24	<b>Inspector Initials</b>	mm
<b>Inspection Number</b>			
<b>Property Address</b>	17368 Piney Point Rd		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**


No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6647



Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17371	Piney Point Rd	
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations
-----	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	Retrofit	E1
--------	--------	----------	----

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

What is the condition of the cover?

Good	Missing	Broken	offset
------	---------	--------	--------

What type of cover is installed?

Vented	Non-Vented
--------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is an isolation valve present?

Yes	No
-----	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6648



Grinder Pump Field Inspection Form

Date of Inspection	11/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17382 Pine Point Rd		
Weather Conditions	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6649



Grinder Pump Field Inspection Form

Date of Inspection	11/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17394 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations
-----	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	Retrofit	E1
--------	--------	----------	----

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

What is the condition of the cover?

Good	Missing	Broken	offset
------	---------	--------	--------

What type of cover is installed?

Vented	Non-Vented
--------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is an isolation valve present?

Yes	No
-----	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

# St. Mary's County MetCom

6650



## Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17408 Piney Point RD		
Weather Conditions	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6651  
WD 31877



<b>Date of Inspection</b>	1/25/24	<b>Inspector Initials</b>	mm
<b>Inspection Number</b>			
<b>Property Address</b>	17484 Piney Point Rd		
<b>Weather Conditions</b>	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


ROOTS GROWING INTO VAULT

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

Grinder Pump Field Inspection Form

6652  
WD 31878 

<b>Date of Inspection</b>	11/25/24	<b>Inspector Initials</b>	mem	
<b>Inspection Number</b>				
<b>Property Address</b>	17486 Piney Point Rd			
<b>Weather Conditions</b>	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE CLEANED OUT

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6653  
WO 31879



Date of Inspection	1/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17515 Pine Point RD		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	<u>Poor</u>	Immediate Action
-----------	------	------	-------------	------------------

VICE GRIPS HOLDING RAIL

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

COVER IS BROKEN AND NEEDS TO BE REPLACED

Repairs needed (if any) and estimated schedule for completion:

VISE GRIPS HOLDING RAIL IN PLACE

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6054  
WO 31880



Date of Inspection	1/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17501 <del>17516</del> PINEY POINT RD		
Weather Conditions	Rain	Snow	Sunny <input type="radio"/> Cloudy <input checked="" type="radio"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE CLEANED OUT.

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6655



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/25/24	<b>Inspector Initials</b>	mm	
<b>Inspection Number</b>				
<b>Property Address</b>	17541 Piney Point Ln			
<b>Weather Conditions</b>	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



6656



Grinder Pump Field Inspection Form

Date of Inspection	1/05/24	Inspector Initials	mm	
Inspection Number				
Property Address	17555 Diney Point Rd			
Weather Conditions	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6657  
31882



<b>Date of Inspection</b>	1/25/24	<b>Inspector Initials</b>	mm	
<b>Inspection Number</b>				
<b>Property Address</b>	17558 Piney Point Rd			
<b>Weather Conditions</b>	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

NEED TO PUT BOLTS IN COVER (NO BOLTS IN COVER)

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6658



Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	Inspector Initials	RHLN	
Inspection Number				
Property Address	17589 piney point Rd			
Weather Conditions	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6659  
WO 31883



Date of Inspection	1/25/24	Inspector Initials	mm
Inspection Number			
Property Address	17594 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

HOME IS VACANT

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

VAULT IS FULL HOME IS VALANT

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



6660



Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	Inspector Initials	RH LN
Inspection Number			
Property Address	17609 piney point Rd		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> <u>Cloudy</u>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6661



Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	Inspector Initials	RH LM
Inspection Number			
Property Address	17619 piney point Rd		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> Cloudy <input checked="" type="checkbox"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**


<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

0662 

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	Inspector Initials	BH/LN	
Inspection Number				
Property Address	17702 piney point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6663



**Grinder Pump Field Inspection Form**

Date of Inspection	1-25-24	Inspector Initials	RH LN	
Inspection Number				
Property Address	17714 <del>#</del> piney point Rd			
Weather Conditions	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

Grinder Pump Field Inspection Form

6973

W/O: 31986.



Date of Inspection	1/31/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17718 Piney Point Rd.		
Weather Conditions	Rain	Snow	Sunny <input type="radio"/> Cloudy <input checked="" type="radio"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input type="radio"/> Good	<input type="radio"/> Missing	<input checked="" type="radio"/> Broken	<input type="radio"/> offset
----------------------------	-------------------------------	---	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Vault in shrubs and sticker thorn bushes

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6664



Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	Inspector Initials	RHLN	
Inspection Number				
Property Address	17750 piney point rd			
Weather Conditions	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6606

WD 31867



Date of Inspection	1/22/24	Inspector Initials	WJ
Inspection Number			
Property Address	17802 Piney Point Rd		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

Loose hanging wires in panel.
Alarm Light and Alarm do not work.

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6665



Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	Inspector Initials	DH
Inspection Number			
Property Address	17878 piney point Rd		
Weather Conditions	Rain	Snow	Sunny <input checked="" type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	No	Unknown, add comments in observations
--------------------------------------	----	---------------------------------------

What type of pump is this?

<input checked="" type="radio"/> Meyers	Barnes	Retrofit	E1
---	--------	----------	----

What is the condition of the vault?

Excellent	<input checked="" type="radio"/> Good	Fair	Poor	Immediate Action
-----------	---------------------------------------	------	------	------------------

What is the condition of the cover?

<input checked="" type="radio"/> Good	Missing	Broken	offset
---------------------------------------	---------	--------	--------

What type of cover is installed?

Vented	<input checked="" type="radio"/> Non-Vented
--------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<input checked="" type="radio"/> Good	Fair	Poor	Immediate Action
-----------	---------------------------------------	------	------	------------------

Is an isolation valve present?

<input checked="" type="radio"/> Yes	No
--------------------------------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6666



Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	Inspector Initials	RH LN
Inspection Number			
Property Address	17890 piney point Rd		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> Cloudy <input checked="" type="checkbox"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="checkbox"/> Unknown, add comments in observations
--------------------------------------	--------------------------	--

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6667  
WO 31884



Date of Inspection	1-25-24	Inspector Initials	RH LH
Inspection Number			
Property Address	17900 piney point rd		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Boots growing inside

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6668



Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	Inspector Initials	RH LN
Inspection Number			
Property Address	17910 piney point Rd		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> Cloudy <input checked="" type="checkbox"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="checkbox"/> Unknown, add comments in observations
--------------------------------------	--------------------------	--

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6669  
WO 31885



Date of Inspection	1-25-24	Inspector Initials	RH LN
Inspection Number			
Property Address	17920 piney point Rd		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> Cloudy <input checked="" type="checkbox"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Roots coming inside vault

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6007



Grinder Pump Field Inspection Form

Date of Inspection	12-24	Inspector Initials	RH LN	
Inspection Number				
Property Address	17930 piney point rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6670  
WO 31886



Date of Inspection	1/24/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	18395 Piney Point Rd.		
Weather Conditions	Rain	Snow	<del>Sunny</del> <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	<u>Retrofit</u>	E1
--------	--------	-----------------	----

What is the condition of the vault?

Excellent	Good	Fair	<u>Poor</u>	Immediate Action
-----------	------	------	-------------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	<u>Poor</u>	Immediate Action
-----------	------	------	-------------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

vault is in bad condition. I&I coming in all around

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6673  
WO 31888



Date of Inspection	1/24/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	18399 Piney Point Rd.		
Weather Conditions	Rain	Snow	<del>Sunny</del> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	Unknown, add comments in observations
--------------------------------------	--------------------------	---------------------------------------

What type of pump is this?

Meyers	Barnes	<input checked="" type="radio"/> Retrofit	E1
--------	--------	---	----

What is the condition of the vault?

Excellent	Good	<input checked="" type="radio"/> Fair	Poor	Immediate Action
-----------	------	---------------------------------------	------	------------------

What is the condition of the cover?

Good	Missing	<input checked="" type="radio"/> Broken	offset
------	---------	---	--------

What type of cover is installed?

Vented	<input checked="" type="radio"/> Non-Vented
--------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	<input checked="" type="radio"/> Fair	Poor	Immediate Action
-----------	------	---------------------------------------	------	------------------

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Vault cover cracked and broken

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6675



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/23/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	18657 Piney Point Rd.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6676



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/23/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	18661 Piney Point Rd.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6677  
WO 31889



<b>Date of Inspection</b>	1/23/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	18960 Piney Point Rd.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input type="radio"/> Yes	<input checked="" type="radio"/> No	<input type="radio"/> Present, but not tested
---------------------------	-------------------------------------	---

Is the visible alarm present and functioning?

<input type="radio"/> Yes	<input checked="" type="radio"/> No	<input type="radio"/> Present, but not tested
---------------------------	-------------------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Both audible and visible alarms not working

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6671  
WO 31887



<b>Date of Inspection</b>	1/23/2024	<b>Inspector Initials</b>	CB LN
<b>Inspection Number</b>			
<b>Property Address</b>	18986 Piney Point Rd.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="checkbox"/> Unknown, add comments in observations
--------------------------------------	--------------------------	--

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6679



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/23/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	19066 Piney Point Rd.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

Grinder Pump Field Inspection Form

668 /  
WO 31890



<b>Date of Inspection</b>	1/23/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	19084 Piney Point Rd.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

# St. Mary's County MetCom

## Grinder Pump Field Inspection Form

6682  
WO 31891



Date of Inspection	1   23   2024	Inspector Initials	LN CB
Inspection Number			
Property Address	1918b Piney Point Rd.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Steady stream of I&I coming in near inlet pipe

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6683

WO 31892



<b>Date of Inspection</b>	1/23/2024	<b>Inspector Initials</b>	LW CB
<b>Inspection Number</b>			
<b>Property Address</b>	19207 Piney Point Rd.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

**What is the condition of the vault?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	<u>No</u>	Present, but not tested
-----	-----------	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**

Alarm light not working

**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6287.

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**



<b>Date of Inspection</b>	1/8/24	<b>Inspector Initials</b>	man
<b>Inspection Number</b>			
<b>Property Address</b>	16127 PINEY POINT RD		
<b>Weather Conditions</b>	Rain	Snow	Sunny
			Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

**What type of pump is this?**

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

**What is the condition of the vault?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**What is the condition of the cover?**

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is an isolation valve present?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



# St. Mary's County MetCom



## Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/8/24	<b>Inspector Initials</b>	mm
<b>Inspection Number</b>			
<b>Property Address</b>	16129 PINEY POINT ROAD		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is the audible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Is the visible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Are there any accessibility issues (shrubs, trees, fences)?**

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

**Other Observations, any "Immediate Action" taken should be described:**



**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6289

# St. Mary's County MetCom

## Grinder Pump Field Inspection Form



<b>Date of Inspection</b>	1/8/24	<b>Inspector Initials</b>	mm
<b>Inspection Number</b>			
<b>Property Address</b>	16165 PINEY POINT RD		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

60290



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/8/24	<b>Inspector Initials</b>	mm
<b>Inspection Number</b>			
<b>Property Address</b>	16168 Diney Point Rd		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

**What is the condition of the vault?**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6608



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	mm	
Inspection Number				
Property Address	16168 Piney Point Rd #2			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6609



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	man	
Inspection Number				
Property Address	16170 Ring Point Rd			
Weather Conditions	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

Yes	<u>No</u>
-----	-----------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).