6855

St. Mary's County MetCom

Grinder Pump Field Inspection Form



Date of Inspection	1-25-24	Inspect	or Initials	RH	Z N
Inspection Number					
Property Address	18104	old TallTimbers Rd			
Weather Conditions	Rain	Snow	Sunny		Cloudy

Does MetCom own the grinder pump?

(Yes No Unknown, add comments in observations	Yes No	Unknown, add comments in observations
-----------------------------------------------	--------	---------------------------------------

What type of pump is this?

		Ī	
Meyers	Dawson	Dotrofit	E4
IVIEVEIS	Barnes	KATTOTIT	J= 1
,	Darrics	INC CI OTT	L1

What is the condition of the vault?

Excellent Good Fair Poor Immediate Action	nt Good Fair Poor Immediate Action
-------------------------------------------	------------------------------------

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented
VCITCU	Non-vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes	No
163	IVO

What is the condition of the electrical panel?

audible ala	rm present and	functioning?		
Yes	No	3 6	Present, but	not tested
visible alar	m present and fo	unctioning?		
Yes	No		Present, but	not tested
	vious signs of I&			Major (gushing
there any ob	_	I (ie. clearwate of I&I (weepin		Major (gushing
o signs of I&I	_	of I&I (weepin	g or trickle)	
o signs of I&I	Minor signs	of I&I (weepin	g or trickle)	
o signs of I&I	Minor signs	of I&I (weepin	g or trickle)	
o signs of I&I	Minor signs	of I&I (weepin	g or trickle)	
er Observation	Minor signs	of I&I (weeping	g or trickle) ken should	be described:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).