

**St. Mary's County MetCom**

6220  
WO 31668



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1   11   2024	<b>Inspector Initials</b> LN CB
<b>Inspection Number</b>		
<b>Property Address</b>	17337 Goddards Ln	
<b>Weather Conditions</b>	Rain      Snow <u>Sunny</u> Cloudy	

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

**What is the condition of the vault?**

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

**What is the condition of the cover?**

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

Yes	<u>No</u>	Present, but not tested
-----	-----------	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

No audible alarm on panel
alarm light still works

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

0972

W/O: 31987



Grinder Pump Field Inspection Form

Date of Inspection	1/30/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17357 Goddards Ln.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/11/2024	<b>Inspector Initials</b>	
<b>Inspection Number</b>			
<b>Property Address</b>	17862 Goddards Ln.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).