

6795



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN UB
<b>Inspection Number</b>			
<b>Property Address</b>	17473 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is the audible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Is the visible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Are there any accessibility issues (shrubs, trees, fences)?**

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------


**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6796



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17485 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

vines growing around and all over vault cover

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6797



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN UB
<b>Inspection Number</b>			
<b>Property Address</b>	17488 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6798  
WD 31936



Date of Inspection	1/8/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17493 River Dr.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Replace vault cover
vault cover has a big crack

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6799  
WO 31937



<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17494 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

ABANDONED, VAULT FULL
-----------------------

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6800



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b> LW CB
<b>Inspection Number</b>		
<b>Property Address</b>	17497 River Dr.	
<b>Weather Conditions</b>	Rain      Snow <u>Sunny</u> Cloudy	

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------


Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6801



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17508 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6802



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17526 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is the audible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Is the visible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Are there any accessibility issues (shrubs, trees, fences)?**

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------


**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



6803



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17537 River Dr		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Customer has large potted plant on top of cover

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6804



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17549 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6805

**Grinder Pump Field Inspection Form**

WD 31938



<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17559 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Audible alarm was not sounding. Visual alarm is functioning
3 thread holes won't accept bolts for vault cover

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6806



Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	Inspector Initials	LN UB
Inspection Number			
Property Address	17575 River Dr.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6807



Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	17580 River Dr.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6808

WO 31940



<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17585 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

<u>Vented</u>	Non-Vented
---------------	------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Bush covering half of vault cover. only has 3 bolts Unable to open panel due to fence installed by customer
--

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6809



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17591 River Dr.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).