
St. Mary's County MetCom



Grinder Pump Field Inspection Form



Date of Inspection	1-25-24		Inspector Initials	LNBH
Inspection Number				
Property Address	45019	Morgon	Brisco G	
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	INO	Unknown, add comments in observations
	110	onknown, and comments in observations

What type of pump is this?

N.A		D	
Mevers	Barnes	Ratrotit	[1
IVICYCIS	(Dailles	Netiont	L.L
			I I

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Miccina	Prokon	offset
0000	iviissiiig	Broken	onset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

			r	
Excellent	Good	Fair	Poor	Immodiate Action
LACCITCITE	dood	1 011	Poor	Immediate Action

Is an isolation valve present?

Voc	NI -
res	INO I

What is the condition of the electrical panel?

		T	T		
Excellent	Good	Fair	Poor	Immediate Action	
	right via				
he audible ala	arm present and	functioning?			
Yes	No	No Present, but not tested			
he visible ala	rm present and	functioning?			
	- present and	Tanctioning:			
Yes	No		Present, but	t not tested	
there any ac	cessibility issues	s (shruhs troos	fancas)?		
		(Sin abs, trees,			
Yes, note iss	sues below in obs	servations		(No)	
there any of	vious signs of 18	Rijio cloarwato	r flow)2		
		xi (ie. cieai wate			
lo signs of I&I	Minor sign	s of I&I (weeping	g or trickle)	Major (gushing	
er Ohservatio	ons, any "Immed	diate Action" tal	on should	ha dassribadı	
er objervati		anate Action tar	Ken should	me described:	
airs needed ((if any) and estin	nated schedule	for complet	cion:	

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).