

6862



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CR
<b>Inspection Number</b>			
<b>Property Address</b>	45260 St. Georges Ave.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	<del>Good</del>	Fair	Poor	Immediate Action
------------------	-----------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

<u>Vented</u>	Non-Vented
---------------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	<del>Good</del>	Fair	Poor	Immediate Action
------------------	-----------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


Other Observations, any "Immediate Action" taken should be described:

bushes next to vault

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6863



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	45266 St. Georges Ave		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	<del>Good</del>	Fair	Poor	Immediate Action
------------------	-----------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	<del>Good</del>	Fair	Poor	Immediate Action
------------------	-----------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6864



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	45272 St Georges Ave.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6865



Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	45278 St. Georges Ave.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Bushes next to vault


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



**St. Mary's County MetCom**

6867



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/8/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	45284 St. Georges Ave.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is the audible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Is the visible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Are there any accessibility issues (shrubs, trees, fences)?**

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6868

WO 31952



Date of Inspection	1/9/2024	Inspector Initials	LN UB
Inspection Number			
Property Address	45319 St. Georges Ave.		
Weather Conditions	Rain	Snow	Sunny
			Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations
-----	----	---------------------------------------

What type of pump is this?

Meyers	Barnes	Retrofit	E1
--------	--------	----------	----

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

What is the condition of the cover?

Good	Missing	Broken	offset
------	---------	--------	--------

What type of cover is installed?

Vented	Non-Vented
--------	------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is an isolation valve present?

Yes	No
-----	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

piece of vault cover got chipped off. part of vault beneath the break also got chipped off

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6869



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1 / 9 / 2024	<b>Inspector Initials</b>	LN UB
<b>Inspection Number</b>			
<b>Property Address</b>	45320 St Georges Ave		
<b>Weather Conditions</b>	<input checked="" type="checkbox"/> Rain	<input type="checkbox"/> Snow	<input type="checkbox"/> Sunny <input type="checkbox"/> Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Unknown, add comments in observations
---	-----------------------------	--

**What type of pump is this?**

<input type="checkbox"/> Meyers	<input checked="" type="checkbox"/> Barnes	<input type="checkbox"/> Retrofit	<input type="checkbox"/> E1
---------------------------------	--	-----------------------------------	-----------------------------

**What is the condition of the vault?**

<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
---	-------------------------------	-------------------------------	-------------------------------	---

**What is the condition of the cover?**

<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Missing	<input type="checkbox"/> Broken	<input type="checkbox"/> offset
--	----------------------------------	---------------------------------	---------------------------------

**What type of cover is installed?**

<input type="checkbox"/> Vented	<input checked="" type="checkbox"/> Non-Vented
---------------------------------	--

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
---	-------------------------------	-------------------------------	-------------------------------	---

**Is an isolation valve present?**

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
---	-----------------------------

**What is the condition of the electrical panel?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is the audible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Is the visible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Are there any accessibility issues (shrubs, trees, fences)?**

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

**Other Observations, any "Immediate Action" taken should be described:**



**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6879  
WO 31953



<b>Date of Inspection</b>	1/9/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	45336 St Georges Ave		
<b>Weather Conditions</b>	Rain	Snow	Sunny Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

**What type of pump is this?**

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

**What is the condition of the vault?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**What is the condition of the cover?**

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is an isolation valve present?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

One Broken bolt stuck in thread hole for vault cover

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6871



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/9/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	45345 St. Georges Ave.		
<b>Weather Conditions</b>	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6872



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/9/2024	<b>Inspector Initials</b>	LN UB
<b>Inspection Number</b>			
<b>Property Address</b>	45383 St Georges Ave		
<b>Weather Conditions</b>	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

**What type of pump is this?**

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

**What is the condition of the vault?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**What is the condition of the cover?**

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is an isolation valve present?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is the audible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Is the visible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Are there any accessibility issues (shrubs, trees, fences)?**

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6873



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/9/2024	<b>Inspector Initials</b>	LN UB
<b>Inspection Number</b>			
<b>Property Address</b>	45401 St. Georges Ave		
<b>Weather Conditions</b>	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

**What type of pump is this?**

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

**What is the condition of the vault?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**What is the condition of the cover?**

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is an isolation valve present?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6874  
WO 31954 

Date of Inspection	1/9/2024	Inspector Initials	LN CB	
Inspection Number				
Property Address	45425 St Georges Ave.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Two bolt holes stripped out on vault cover

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



6875



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/9/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	45438 St Georges Ave.		
<b>Weather Conditions</b>	<input checked="" type="checkbox"/> Rain	<input type="checkbox"/> Snow	<input type="checkbox"/> Sunny <input type="checkbox"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Unknown, add comments in observations
---	-----------------------------	--

What type of pump is this?

<input type="checkbox"/> Meyers	<input checked="" type="checkbox"/> Barnes	<input type="checkbox"/> Retrofit	<input type="checkbox"/> E1
---------------------------------	--	-----------------------------------	-----------------------------

What is the condition of the vault?

<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
---	-------------------------------	-------------------------------	-------------------------------	---

What is the condition of the cover?

<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Missing	<input type="checkbox"/> Broken	<input type="checkbox"/> offset
--	----------------------------------	---------------------------------	---------------------------------

What type of cover is installed?

<input type="checkbox"/> Vented	<input checked="" type="checkbox"/> Non-Vented
---------------------------------	--

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Immediate Action
---	-------------------------------	-------------------------------	-------------------------------	---

Is an isolation valve present?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
---	-----------------------------

**What is the condition of the electrical panel?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is the audible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Is the visible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Are there any accessibility issues (shrubs, trees, fences)?**

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

0876  
WO 31955 

<b>Date of Inspection</b>	1/9/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	45441 St Georges Ave.		
<b>Weather Conditions</b>	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

**What type of pump is this?**

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

**What is the condition of the vault?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**What is the condition of the cover?**

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is an isolation valve present?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**

Audible alarm was not sounding. visual alarm light still lights up

**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6877



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/9/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	45450 St Georges Ave.		
<b>Weather Conditions</b>	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6878



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/9/2024	<b>Inspector Initials</b>	LN UB
<b>Inspection Number</b>			
<b>Property Address</b>	46451 St Georges Ave.		
<b>Weather Conditions</b>	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

**What type of pump is this?**

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

**What is the condition of the vault?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**What is the condition of the cover?**

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is an isolation valve present?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



St. Mary's County MetCom

6879



Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	45455 St Georges Ave		
Weather Conditions	<u>Rain</u>	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6880



Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	48461 St. Georges Ave.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6881



Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	Inspector Initials	LN UB
Inspection Number			
Property Address	45462 St. Georges Ave.		
Weather Conditions	<input checked="" type="radio"/> Rain	<input type="radio"/> Snow	<input type="radio"/> Sunny <input type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6882  
WO 31956 

Date of Inspection	1/9/2024	Inspector Initials	LN CB
Inspection Number			
Property Address	<del>1545</del> St Georges Ave		
Weather Conditions	Rain 45473	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	Unknown, add comments in observations
--------------------------------------	--------------------------	---------------------------------------

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

one bolt stuck in vault cover

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).